



A Furukawa Company

Product Change Notice/
Product Recall Notice

1. Supplier Information OFS 10 BrightWave Boulevard, Carrollton, GA 30117 Contact: Xavier Chiron (770) 798 - 2208 xchiron@ofsoptics.com		2. Product Change/ Recall Notice No. 2016-0003-1 D	2a. Include on www.ofsoptics.com Yes
3. Issue Date of Change/Recall January, 2016		4. System & Product Description EZ-Bend® jumpers package change	
5. New Product ID JRVD c 001 eee fff nnn F Where: <ul style="list-style-type: none"> • JRVD: <ul style="list-style-type: none"> • Riser 3.0 mm Ruggedized I/O (Simplex Only) • EZ Bend • color White or Black • 001 Simplex • eee Connector end SCA, SCU, LCA, LCU or UNC (un-connectorized) • fff Connector end SCA, SCU, LCA, LCU • nnn Length (up to 50 feet) Above 50 feet, the standard package will be a spool.		6. Old Product ID JRVD c 001 eee fff nnn F Where: <ul style="list-style-type: none"> • JRVD: <ul style="list-style-type: none"> • Riser 3.0 mm Ruggedized I/O (Simplex Only) • EZ Bend • color White or Black • 001 Simplex • eee Connector end SCA, SCU, LCA, LCU or UNC (un-connectorized) • fff Connector end SCA, SCU, LCA, LCU • nnn Length (up to 50 feet) Up to 150 feet, the jumper was coiled.	
7. Associated Products or Changes Affected The package of the EZ-Bend riser 3.0 mm jumper was changed to a spool for length above 50 feet. The new package allows a quicker and easier installation than the previous package (coiled jumper).			
8. Drawing No. D08AK1058		9. Product Change Classification D	
10. Classification Substantiation Package change.			
11. Reason(s) for Change/Recall Improves installation process preventing kinks and crosses when pulling the assembly.			
12. Description of Change/Recall Change of the package for lengths above 50 feet.			
13. Effect of Change/Recall Doesn't impact assembly performance.			
14. Material/Product Affected JRVD c 001 eee fff nnn F for lengths above 50 feet.			
15. Documentation Affected Data Sheet Revisions to EZ-Bend Jumpers.			
16. Supplier Implementation Date January, 2016		17. Modification Completion Date January, 2016	
18. Modification/Recall Location N/A			
19. Modification/Recall Cost N/A			
20. Location and Quantity of Equipment N/A			
21. Attachments N/A			
22. Comments			

Table 1 Product Code Changes

JRVDW001SCAUNCxxxF
JRVDW001SCASCAxxxF

JRVDW001SCUUNCxxxF
JRVDW001SCUSCUxxxF

JRVDK001SCAUNCxxxF
JRVDK001SCASCAxxxF

JRVDK001SCUUNCxxxF
JRVDK001SCUSCUxxxF

JRVDW001LCAUNCxxxF
JRVDW001LCALCAxxxF

JRVDW001LCUUNCxxxF
JRVDW001LCULCUxxxF

JRVDK001LCAUNCxxxF
JRVDK001LCALCAxxxF

JRVDK001LCUUNCxxxF
JRVDK001LCULCUxxxF

JRVDW001LCASCAxxxF

JRVDW001LCASCUxxxF

JRVDW001LCUSCAxxxF

JRVDW001LCUSCUxxxF